
Main parts needed to mount the extrusion


Aluminum profile(A)



End cap (B)



End cap with hole (C)



Cover (D)



LED strip(E)

Tools needed for mounting:


screwdriver

NOTE! All LED strips must be connected to a 24V power supply.


IMPORTANT: The manual presents the simplest mounting procedure.

More mounting procedures and related accessories can be consulted from *LEDLUZ* lighting.


1. Insert the end caps (B) and (C), then mount the aluminum profile (A) on the ceiling.



2. Apply a layer of plaster to the profile and ceiling, and then paint the surface to finish.



3. Mount the LED strip (E), insert the cover (D), lead out the power cable.



4. Run the cable to the power source, connect power.

